

TECHNICAL BULLETIN

New Sized Breather Cap (MX000686)

Issue/Action: The breather cap shipped with all hydraulic operators to replace pre-installed red vent plug has been discontinued and replaced with a new breather cap beginning May 2018.

Operators Affected: All hydraulic operators with pump pack equipped.

Beginning May 2018, HySecurity will be using a redesigned 40 micron 0.375" breather cap (Figure 1) to replace the pre-installed red vent plug installed on shipped hydraulic operators. The new breather cap functions identically like previously provided breather cap (Figure 2), but is smaller form factor.



Figure 1. New Breather Cap



Figure 2. Old Breather Cap